




## Ford 8.8 Fill Plug Location

Pictured below is the fill plug for the Ford 8.8, its location is indicated by a white arrow. Please note this is on the front of the differential located near the pinion. The 8.8 must be filled from this location, not from an aftermarket differential cover.



**Failure to fill from this location will cause over-filling of the differential and possible damage to the axle and void warranty!! Or pending pinion angle, under filling of the axle. All ford 8.8 axles should have 2.85-3 quarts. If you have a pinion angle above 15 degrees 3.5 quarts is recommended however it may release some fluid out of the breather.**